


## QuickLock Quick change system



### 6 GOOD REASONS

- tool-less quick change system  
can be used with UR3/UR3e, UR5/UR5e and UR10 (not for UR10e and UR16e)
- suitable for different mounting positions
- high repetition accuracy of the positioning
- very easy handling
- location flexible LWR-/HRC solution
- corrosion-resistant & operationally reliable

### FACTS AND FIGURES

	Consist of	<b>a base holder and a plate for the robot base</b>
Dimension basic holder (LxWxH)		440x312x59 mm
Dimension incl. tension lever (LxWxH)		440x370x85 mm
Weight		ap. 32 kg total

### SUITABILITY

- Applications
- semi-automated production lines in small parts production
  - flexible pick and place tasks
  - flexible loading of machine tools
  - collaboration on (ECO/Cell and ECO/Line) manual work station
  - flexible, portable robot applications (dosing, measuring, testing)

### FEATURES

- ergonomic construction
- manual one-handed unlocking
- safety position

Basic holder

&

Plate for Robot foot

